


Typical Vehicle Installation



VDU to Radio Data, I/O & Power Cable

2001 to present status


- •Installed on 1 Subdivision for proof of concept
- •Installed infrastructure on 10 Subdivisions 150 vehicles.
 - Entire 33000 mile system GPS surveyed in 6 months.


2002-2003 plan

- •Install HLCS system in 360 vehicles.
- •Install infrastructure on 47 Subdivisions.
 - •Begin locomotive testing.
 - •Change management process.




If the GPS database and the field database are identical. The system will work as intended.







If the switch location of the Coal Spur switch is moved it must be updated in the GPS database!

The GPS database must be accurate or alarms may not occur when they should!






This data may be used to provide information to trains as well as MOW. Improper data could create a lap of authority. If train A has an electronic authority to proceed from CTC Surrey Jct to the Coal Spur switch the system will allow the train to proceed to the old coal spur switch location.



An opposing train with a hand written authority instructing them to proceed to the Coal Spur has authority to the new coal spur switch location.



In this example a misunderstanding between two systems has created a lap of authority between the Old and New coal spur switch locations. Proper reporting of some changes before they go into effect is critical to the safety of the system.

Changes that affect the safe movement of trains and equipment must be reported to the NCS group. Changes are the relocation, removal, or addition of:

- 1. Milepost signs.
- 2. Speed signs.
- 3. Switches including making a switch electric lock.
- 4. Grade crossings.
- 5. Grade crossing protection.
- 6. Signals.
- 7. Authority type (i.e. TWC to CTC).
- 8. Clearance joint location.


Reporting methods and equipment

- 1. VDU
- 2. Approved GPS handheld device.
- 3. Approved linear measuring device.


	NCS CHAN	ge managemei	NT FORM	
1. Division Menu 🖢	2. Subdivision	3. Line Segment	4. Station of Change	
5. Detailed Description of Change		6a. Date of Report 6b. Change Type Meru	6c. Change Made by 6d. Title 6e. Phone Number	
		7a. Date of Report 7b. Report Method Mervi	7c. Report Made by 7d. Title 7e. Headquarters Location	


Fill out the Change Management Form NCS 0002 Rev 01

8. Feature Mercu	9. Milepost	10. Track Name Merci	11. Operation Type Memi	12. Change Type Merai
13. Latitude	. "	14. Longitude	. "	15. Altitude Feet
Switch Type Memi	Turnout Type Meroi	Turnout Direction Meroi	☐ Bungalow ☐ Case	Trackside Location of Case or Bungalow Menu
Sign Type Memi	Other Sign Type	Sign Trackside Meroi	10	
Wayside Type Meroi	Other Wayside Ty	ype Trackside Meroi	☐ Bungalow ☐ Case	Trackside Location of Case or Bungalow Memi
Structure Type Memi	Bridge Type Over/Under Pass Number of Lanes Meroi Meroi		Angle to Track Merci	
Grade Crossing Public	Protection Type Memi	Number of Lanes Merca	Angle to Track Menu	Trackside Location of Case or Bungalow Menu
	Street Name	DOT Number	☐ Bungalow ☐ Case	Street side Location of Case of Bungalow Menu
	Highway Name	City	County	State
Signal Head Type Meroi	Signal Direction Menu	Signal Fixture Mercu	Trackside Meroi	Signal Number
	Signal Aspect	Signal System T	ype Bungalow Case	Trackside Location of Case or Bungalow Memi




While making the track change and before releasing the track to the dispatcher.





Line the on track vehicle GPS antenna perpendicular to the changed feature.





Call the NCS Hotline.



When the NCS Change Specialist gives the OK, press the "MARK" button on the VDU once every 30 seconds for 5 minutes.



Some changes do not affect the safe movement of trains and equipment. These changes are important because these assets are being kept track of in a database. These changes can be reported to the NCS group after the change goes into effect.

- 1. Switch size.
- 2. Switch change from hand throw to spring.
- 3. Signal head change from searchlight to color light.
- 4. Grade crossing protection from flasher to flasher and gates.
- 5. Pedestrian crossing removed.

Changes not affecting the movement of trains and MOW can be reported 4 different ways:

- 1. Fill out the Change Management Form NCS 0002 Rev 01 and fax it to a NCS Change Management Specialist.
- 2. Fill out the Change Management Form NCS 0002 Rev 01 and transfer the information to the electronic version and e-mail it to NCS Change Management.
- 3. Access the NCS Change Management Web page on the BNSF Railway Intranet and enter the feature change information in the web format.
- 4. Call the Hot line phone and relay the information off the Change Management Form NCS 0002 Rev 01 to a change management specialist.